


JOHN CARLON, PRESIDENT





4 weeks
@ Dos Rios






**Willow Bend Restoration Area
Cross Section
Colusa County, California**



Cross Section 1 (feet)
20x exaggeration


— Sacramento River
— Restoration
— Remnant



Elevation source: COE 2 foot river contours

Cross Section 2 (feet)
20x exaggeration

— Sacramento River
— Restoration
— Remnant



Elevation source: COE 2 foot river contours

SACTO R AT COLUSA WEIR (CREST 61.8') (CLW)

Date from 05/09/2002 14:52 through 05/19/2017 14:55 Duration : 2567 days

Max of period : (02/19/2017 17:15, 68.68) Min of period: (12/15/2002 11:30, 61.3)

